Cristina Juanos Cabanas, Tchien Minh Tang, Pierre De Cannière

Bending Observed on the Carbon Steel Liner of the Pre-stressed Concrete Primary Containment of a Nuclear Reactor: Safety Assessment





SUMMARY


- Introduction
- Historic information
- Experience feedback
- Technical analysis
 - Historical
 - Causes of the bending
 - Safety issues
- Conclusions







• 7/09/2014:



HISTORIC INFORMATION





FIGURE 2 : DISPOSITION DES ANCRAGES DANS LE LINER.



EUROSAFE 2016

HISTORIC INFORMATION

- Design of the concerned unit
 - Loads considered (primary containment)
- Construction of the concerned unit
 - Carbon steel liner used as a lost formwork
- Regarding CONFINEMENT safety function
 - Carbon steel liner: "tightness" safety function
 - Pre-stressed reinforced concrete: "structural" safety function
- \rightarrow Both are key elements when talking about nuclear safety





EXPERIENCE FEEDBACK Early 2015:

- Bel V checked the existence of similar events worldwide and in Belgium
 - International return of experience: bending reported had a maximal surface of around 1 m²
 - National experience: local deformation (bending 1m long and 50 cm to 60 cm high) of the carbon steel liner observed in its lower part (1992)





TECHNICAL ANALYSIS

• Bel V carried out a safety assessment to evaluate:

- the upholding of the tightness safety function (and so the upholding of the bending) in accidental conditions
- the upholding of the structural safety function of the pre-stressed reinforced concrete primary containment in accidental conditions
- Determine causes / origin
- Evolving phenomenon





TECHNICAL ANALYSIS - HISTORICAL • 7/09/2004: E Vue de face juin 2015 avec courbes d'épaisseur Conclusion 6.878 Sur toute la cloque, le relevé AT STOP LTO de juin 2015 se superpose 1.131 au relevé septembre 2014. Les écarts minimes entre les 2 relevés entrent 1.000 dans la tolérance de l'appareil de mesure de métrologie (+/- 2mm près). 1.14 Gonflement maximum (zone rouge) : 0.14m Altitude approximative centre cloque : 81.75 -1.00 Distance centre cloque / SAS : 2.85m 4.125 Largeur zone cloque : 2.68m Hauteur zone cloque : 1.85m Surface approximative zone cloque : 4.31m² Volume approximatif : 0.176 m³ Ν Coupes CLOQUE liner 20' 20^{-1} E po-Travers026- 82,700 m Coupe-Travers028- 82.900 m Projet : Relevé cloque liner CNT1 - juin 2015 Responsable : Antoine GUERIN - LTO No Electrabel Dossier GEOTOP 2015-5119 Date levé Indice Schelle: variable plan Contact : STOFFE Ph. 0475/76.35.68 23/06/2019 1 Format A3





TECHNICAL ANALYSIS - CAUSES

- Thrust of the fresh concrete on the non-supported carbon steel liner used as formwork
- Fatigue phenomenon caused by the thermal loads?
- Defect in the pre-stressed reinforced concrete primary containment ?
- Bel V asked the Licensee to carry out necessary inspections and investigations





TECHNICAL ANALYSIS – TIGHTNESS SAFETY FUNCTION


CONTOURS lr equivalent stra Time 7 Upper surf. Comput Ref Ld Min = 2.1668 Max = 0.0122 Liner + béton 0.003393-0.0045173 0.006765 0.0078890 0.009013 0.0101369 0.0112608 the d liner Т ssion From TIS1/4NT/0320140/000/01 Figure 8 : déformations plastiques dans le liner en peau externe- AMH. ; OK Figure 3 : Modèle EF pour l'étude du l EUROSAFE

Vu de dessus (coupe dans l'épaisseur)

2016



TECHNICAL ANALYSIS – STRUCTURAL SAFETY FUNCTION



ΒΕΙ 🖌

EUROSAFE 2016

CONCLUSIONS

- On 7/09/2014: Bending (2.7 m wide, 1.9 m high, maximum curving of 14 cm) was observed on the liner of the primary containment
- National and international literature did not show similar reported bendings





CONCLUSIONS

- Bel V carried out a safety assessment:
 - Upholding of the tightness safety function of the liner (and so the upholding of the buckling) in accidental conditions:
 - Global type A pressure test in 2005 and 2016
 - Ultrasonic tests on the welds in 2015
 - Magnetic controls of the liner in 2015
 - Finite elements calculation of the liner
 - 3D scan of the liner in 2014, in 2015 and in 2016
 - Bel V concluded that the tightness safety function is ensured

EUROSAFE



CONCLUSIONS

- Bel V carried out a safety assessment:
 - Upholding of the structural safety function of primary containment in accidental conditions by demonstrating no damage on the primary containment:
 - Two drillings inside of the buckling through the carbon steel liner
 - Post-tensioning losses were checked
 - Bel V concluded that the structural safety function is ensured









